## C-A OPERATIONS PROCEDURES MANUAL

## ATTACHMENT

# 4.56.ar RHIC 8z1 Sweep Checklist

Text Pages 1 through 6

Hand	Processed	C	hanges

HPC No.	<u>Date</u>	Page Nos.	<b>Initials</b>	
_04-03	11/20/03		PFI	
	Approved by: _	Collider-Accelerator I	Department Chairman	Date

P. Ingrassia

## CA-OPM-ATT 4.56.ar RHIC Zone 8z1 Sweep Checklist -- **TEAM A**


Team Leader (TLA)	Sweeper#2 ( <b>S2</b> )
Sweeper#3 (S3)	
Time:	Date:

#### Note:

IF any workers are encountered during the sweep, THEN contact the OC to see if the sweep should be aborted. Workers shall leave the enclosure WITH the sweep team. IF the workers crash out of the enclosure AND do not exit with the sweep team, THEN the sweep shall be re-started.

#### **Prerequisites**

- Three persons to perform the sweep, one person may be supplied by the Phenix collaboration
- Phenix 8z1 Sweep Checklist (TEAM A) (two pages/ three sides)
- Zones 7z1 and 8z2 should be searched and secured first
- Required Tools: at least three flashlights
- Walkie-talkies (one each for TL), and TLDs (one for each C-AD staff member)
- All Doors closed THEN 8z1 set to Controlled Access
- The lower scaffold (west wall) must be in the down position
- Keys: One Sweep Reset key S/R015 (Team Leader), and two Controlled Access keys CA014 (S2+S3)
- Lock, & Red Tag for Muon Steel South East third level Ladder barricade
- TLA MUST be someone who will readily climb the ladders and walk the upper platforms



**CONTINUED ON REVERSE SIDE** 

#### Note 1:

Before beginning the sweep:

- Contact the experiment shift leader to tell them a sweep will be performed.
- Ask the experiment to turn off their magnet(s)
- IF magnet(s) cannot be turned off THEN carry no ferrous objects while sweeping near the magnet(s) and obey postings and fencing to stay away from fields greater than 500 gauss.

#### Note 2:

The shield block wall must be completed and inserted before the sweep may begin.

#### Note 3:

IF EITHER THE EAST OR WEST CARRIAGE, OR BOTH CARRIAGES ARE NOT FULLY INSERTED THEN THE SWEEP TEAMS MUST SWEEP THE INTERIOR "GROUND LEVEL" PORTION OF THE DETECTOR.

Chec	k	
	1	TLA contacts Phenix Shift Leader (person in charge) and gets two Phenix staff members to assist in the sweep. (a
		total of six Operations group members may be used instead)
	2	TLA instructs the two Phenix staff members that their role is:
		• To stand static watch as assigned (S3 position in the SE corner of the hall), and
		• To challenge any person, other than the 4 sweep team members, to come to their position and await to be escorted out of the hall.
		<ul> <li>TLA gives each Phenix staff member a CA key and a flashlight.</li> </ul>
	3	Sweep team goes to 8GE1 (inner chain link fence gate) in the Phenix experimental hall building and TL asks MCR
		for simultaneous release
	4	TLA opens 8GE1 gate by turning the CA014 key in the Controlled Access key-switch AT THE INNER CHAIN
		LINK FENCE GATE while operator in MCR presses simultaneous release for 8GE1.
	5	Sweep Team passes through 8GE1.
	6	Sweep Team splits up – Team A to the South, Team B to the North
	8	TLA and S2 and S3 walk to mouth of labyrinth for gate 8ED1.
	9	TLA instructs S3 to stand static watch at the mouth of the labyrinth for gate 8ED1.
	10	TLA walks through "parafin door" to gate 8ED1.
	11	TLA resets gate 8ED1 by turning the S/R015 key in the RESET keyswitch next to the gate.
		TLA observes the gate reset lamp lights.
	13	TLA STARTS SWEEP by turning the S/R015 key CW in the SWEEP key-switch on 8XCS1 next to 8ED1 gate.
		(The PASS box in step 11 contains both SWEEP and RESET keyswitches).
		TLA observes AREA SECURED lamp blink once.
		TLA sweeps up the labyrinth and joins S2 & S3.
	16	TLA instructs S2 to go to the muon steel panels in the SE corner of the hall. TLA walks to the southwest
		side of the experimental hall while S3 remains static in SE corner.
	17	TLA goes to the SW corner of the hall and shines the flashlight in between each muon steel panel to
		search for personnel. TL instructs S2 to do the same flashlight search between the steel panels.
		TLA instructs S2 to search SE corner tower ladder and the floors above .
	19	S2 looks to see if the barricade is in place on the top floor to block access to the top of the muon steel.

# CONTINUED ON NEXT SHEET

	Note 4:
	IF the west carriage is opened or the walkways not accessible, THEN TLA sweeps level 2 platform in the South East corner.
a	TLA climbs ladder to second level platform of west carriage and walks north to meet TLB
b	TLA and TLB climb ladder to third level platform of west carriage.
c	TLA sweeps third level platform while TLB climbs to fourth level and sweeps
d	TLA joins TLB in north west corner of third level and TLA and TLB sweep down to level 2.
e.e	TLA sweeps south on level two and down the southwest ladder to the southwest corner of the hall.
-	TLA sets second check station by turning S/R015 key CW in the SWEEP key-switch on 8XCS2 in SW corner of
	Phenix hall.
26	TLA observes AREA SECURED lamp blink once.
_ <del>_</del> 27	•
_2, 29	·
	THEN he/she enters the detector to search for personnel
_30	
_31	
32	
_3 <u>2</u>	· · ·
_	TLA sweeps the south end of the platform and landing, while TLB does the same at the north end.
_35	1
_	TLA sweeps the south end of the platform and landing, while TLB does the same at the north end.
_37	•
f	TLA sweeps the south end of the platform and landing, while TLB does the same at the north end.
_ _g	TLA and TLB go down to ground level on their respective ladders.
	TLA calls to TEAM A (S2 & S3) and tells them to sweep 8GE1. Team A meets Team B at the gate
_	TLA ENDS SWEEP at fifth check station (8XCS5) by turning S/R015 key in the SWEEP
	keyswitch on the box inside the gate
40	TLA observes AREA SECURED lamp remains lit.
_	TLA calls MCR for simultaneous release at 8GE1 (inner chain link gate).
_	Sweep Team sweeps out 8GE1.
_	TLA closes the 8GE1 plug door by doing the following:
_	set plug drive motor energy disconnect switch to the ON position
	insert and turn the S/R015 key in the drive motor enable keyswitch (RHIC Safety Systems 8GE1
	Plug Door Lockout)
	PRESS AND HOLD the close pushbutton
	IF the door does not move THEN pull the red crash button on the detector side of the plug door.
44	WHEN the plug is closed, TL resets the 8GE1 gate by turning the S/R015 key in the
_	RESET keyswitch.
45	TLA observes Gate Reset lamp light
_ _46	TLA contacts MCR to verify 8z1 sweep is good and gates (8GE1 and 8ED1) are reset
	Note:  If Area Secured Lamp Is Not Lit Then contact MCR to verify if sweep is good

## CA-OPM-ATT 4.56.ar RHIC Zone 8z1 Sweep Checklist -- **TEAM B**


Team Leader (TLB)	Sweeper#2 ( <b>S2</b> )
Sweeper#3 ( <b>S3</b> )	
Time·	Date:

#### Note:

**IF** any workers are encountered during the sweep, **THEN** contact the OC to see if the sweep should be aborted. Workers shall leave the enclosure **WITH** the sweep team. **IF** the workers crash out of the enclosure **AND** do not exit with the sweep team, **THEN** the sweep shall be re-started.

#### **Prerequisites**

- Three persons to perform the sweep, one person may be supplied by the Phenix collaboration
- Phenix 8z1 Sweep Checklist (TEAM B) (one page/two sides)
- Zones 7z1 and 8z2 should be searched and secured first
- Required Tools: at least two flashlights
- Walkie-talkies (one each for TL) and TLDs (one for each C-AD staff member)
- All Doors closed THEN 8z1 set to Controlled Access
- The lower scaffold (west wall) must be in the down position
- Keys: One Sweep Reset key S/R015 (Team Leader), and Two Controlled Access keys CA014 (S2 +S3)
- Lock, & Red Tag for Muon Steel North East third level Ladder barricade
- TLB MUST be someone who will readily climb the ladders and walk the upper platforms



### **CONTINUED ON REVERSE SIDE**

#### **Note 1:**

# IF EITHER THE EAST OR WEST CARRIAGE, OR BOTH CARRIAGES ARE NOT FULLY INSERTED THEN THE SWEEP TEAMS MUST SWEEP THE INTERIOR "GROUND LEVEL" PORTION OF THE DETECTOR. Note 2:

TLB MUST NOT reset check station THREE until he/she hears it is ok to do so from TLA

	TEB MOOT FOR THOSE SWICH TIMES AND INCIDENCE IN THE ON TO ACCOUNT TEM
<u>Check</u>	
1	Team B enters 8z1 through 8GE1 along with Team A
2	Sweep teams split up, Team A to the South, Team B to the North
3	TLB instructs S3 to stand static watch "at ground level" inside 8GE1 (map position 5).
4	TLB instructs S2 to walk to the NE corner of the hall to search between steel panels
5	TLB walks to NW corner (map position 3) of the enclosure.
6	TLB shines the flashlight between each muon steel panel to search for personnel.
	TLB instructs S2 to do the same flashlight search between the steel panels.
7	S2 looks up the NE ladder to search for personnel on the floors above.
8	S2 looks to see if the barricade is locked in place on the third floor to block access to the top of the muon steel
9	IF the barricade is not in place THEN S2 climbs the ladder, searches the top of the north muon steel, installs
	and locks the barricade in place, then returns to ground level.
10	TLB calls S2 to come to the NW corner of the enclosure.
	S2 stands static watch in the NW corner.
	TLB searches the back of the detector along the west wall of the enclosure.
	TLB looks up tower ladder in NW corner of enclosure to search the floors next to north
13	muon steel panels
	-
-	Note 3:
	ne west carriage is opened or the walkways not accessible, THEN TLB sweeps levels 2 & 3 platforms as well as
the l	evel 4 walkway
a	TLB climbs ladder to second level platform of west carriage and waits to meet TLA
b	TLB and TLA climb ladder to third level platform of west carriage.
c	TLB climbs to fourth level and sweeps fourth level while TLA sweeps third level
d	TLB climbs down and meets TLA in north west corner of third level and TLA and TLB sweep
	down to level 2.
e	TLB sweeps down to level 1 using the ladder in the northwest corner16 TLB resets check station 3 after
	hearing form TLA that check station 2 was reset.
17	TLB sets third check station by turning the S/R015 key CW in the SWEEP key-switch on
	8XCS3 in the NW corner of the Phenix hall.
18	TLB observes AREA SECURED lamp blink once.
	TLB sweeps to NE corner of the enclosure – IF the East or West carriage is withdrawn,
	THEN he/she enters the detector to search for personnel
20	TLB sweeps to NE corner and joins TLA.
<u>2</u> 3	TLA and TLB climb the ladder in the NW corner to level four.
21	
23	TLB searches then entire enclosure from the catwalk then sweeps back and joins TLA.
<u>23</u>	TLB resets check station 4 (8xCS4) while TLA sweeps south on the fourth level catwalk along the east wall.
	TLB sets fourth check station by turning the S/R015 key CW in the SWEEP key-switch on 8XCS4
23	
26	on the east wall above 8GE1.
${27}^{26}$	TLB observes AREA SECURED lamp blink once
27	TLB sweeps the north end of the platform and landing, while TLA does the same at the south end.
28	TLB and TLA go down to level three on their respective ladders.
29	TLB sweeps the north end of the platform and landing, while TLA does the same at the south end.
30	TLB and TLA go down to level two on their respective ladders.
f	TLB sweeps the north end of the platform and landing, while TLA does the same at the south end.
g	TLB and TLA go down to ground level on their respective ladders.
31	TLB sweeps to 8GE1 and calls S2 to join him/her and S3 at 8GE1.
32	Team B awaits Team A so that all will exit together.